Qty:



Friday, 04/04/2008 9:58:52 AM Date

User: Julie Lecocq

Process Sheet

Drawing Name

Customer : CU-DAR001 Dart Helicopters Services Job Number : 38408

Type

: 12784 **Estimate Number**

P.O. Number

: 04/04/2008 S.O. No. : This Issue

: NC Prsht Rev.

: 04/04/2008 First Issue : 37812 Previous Run

Written By

Checked & Approved By

Comment

Est Rev:B As per Rev C 07-07-09 JLM

Est Rev:C

: Est Rev:A New Issue 07-03-08 ec

As per Rev D 07-09-09 JLM Verified By:EC

: SMALL /MED FAB

Part Number : D35649 : D3564 REV D **Drawing Number** : N/A Project Number : D

: WEARPAD

Drawing Revision Material

: 18/04/2008 **Due Date**

Each Um:

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

M304S16GA

304/316 .063 Sheet



1.1550 sf(s)/Unit

Total: 23.1000 sf(s)

M304S16GA Stainless steel sheet 0.063" thick

107676 X 22 = 26

Batch:

2.0

WATER JET

FLOW WATER JET



Comment: FLOW WATER JET

1-Cut as per Dwg D3564 *****(D3564-1F)*****

Dwg Rev: D Prog Rev:

B 8-4-10



2-Deburr if necessary

3.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



B8-4-10

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

QC8

SECOND CHECK



Comment: SECOND CHECK

5.0

BRAKE NO

NC BRAKE



Comment: NC BRAKE

Form on Brake as per Dwg D3564 using Jigs DT 8 79 and DT 8 155

08/04

Dart Aerospace Ltd

Dail Aci	Ushaci	e Liu							
W/O:	-	The state of the s	V	VORK ORDER CHANGE	S				1.5
DATE	STEP	PROC	EDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				×					
FA.									2
Part No		PAR #:	Fault Ca	tegory:				Date:	
NCR:		W	ORK OR	DER NON-CONFORMA					4
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verific Section		Approval Chief Eng	Approval QC Inspector

NOTE: Date & initial all entries

Date: Friday, 04/04/2008 9:58:52 AM User: Julie Lecocq **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: WEARPAD Part Number: D35649 Job Number: 38408 Job Number: Seq. #: Machine Or Operation: Description: Form Joggle as per Dwg D3564 on brake using Jig DT % (5 SB 08/04/17(6.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP Ensure joggle as per dwg D3429 LARGE FAB 1 7.0 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 Qty Description Batch M107051 2059B Hardcoat Weld hardcoat as per Dwg D3564 M loc 115 8.0 QC10 Comment: VISUAL INSPECTION OF GROUND WELDS 9.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP POWDER COATING POWDER COATING 10.0 06442 Comment: POWDER COATING Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3 11.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 12.0 PACKAGING PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 1=121X

Da	rt A	er	os	na	e	Ltd
Bur Sale		101	00	~~	~~	

W/O:			WORK ORI	DER CHANGES		- 1	LE H		
DATE	STEP	PRO	CEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						100			
						- The			
Part No	:	_PAR #:	Fault Category:	NC	R: Yes	No DQA	\:	Date:	
					QA:	N/C Closed	l:	_ Date: _	

NCR:				Corrective Action Section B				
DATE	STEP	Description of NC Section A	Initial Action Description S		Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspecto
		E the						
			Wing.			L. Top		
	1		200		-			
						B. 187		
			565					
	The second		le la					
			March 1		-			

NOTE: Date & initial all-entries

Date:

Friday, 04/04/2008 9:58:52 AM

User:

Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: WEARPAD

Job Number: 38408

Part Number: D35649

Job Number:



Seq. #:

Machine Or Operation:

Description:

13.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



N 08,04,22

Dart Ae	rospace	Ltd:							
W/O:		7 7		W	ORK ORDER CHANG	GES	The state of		
DATE	STEP	2	PROC	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
							5-1		
			7	4.4					
		- I							
Part No			PAR #:	_ Fault Cate	egory:	NCR: Yes N	lo DQA:	Date:	
				100		QA: N/	C Closed:	Date: _	
NCR:			W	ORK ORD	ER NON-CONFORM	ANCE (NCR)			
DATE	STEP	Descriptio	n of NC	Corrective Action Section B			Verification		Approval
DATE	SIEF	Section	ı A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
				E.				5.4	
		= 3							
							4		
							No.		

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order: 38	408
Description: Wearshoe	Part Number: D3	3564-9
Inspection Dwg: D3564 Rev: D	Pag	e 1 of 1

		X	First Article	F	rototyp	е	
Drawing Dimension	Tolerand	e	Actual Dimension	Accept	Reject	Method of Inspection	Comments
3.227	+/-0.010)	3,239	×			
2.432	+/-0.010)	2434	*			
2.50	+/-0.030		251	36			
6.000	+/-0.010)	6.000	K		1 P	
12.104	+/-0.010)	12.104	4			
18.000	+/-0.010)	000.81	X			
18.000	+/-0.010		18.000	36			
18.00	+/-0.030)	00,81	X			
9.00	+/-0.030	E	9,00	K			
11.50	+/-0.030).	11.50	×			
0.300×0.300	+/-0.010	Y.	304X34	36			
Ø0.188	+0.005/-0.0	001	, 191	×			
R0.375	+/-0.010)	375	*			
0.063	+/-0.010		,062	مر			
	_						
	B 8-4-10		Audited by: Date:	Roylu		totype Approva Dat	

H:\FORMS\Quality Assurance\approved QA\FAI rev	ORMS\Quality Assu	rance\approved	QA\FAI revI
--	-------------------	----------------	-------------





